

TS 4000
TS 4000 S

107754-02




GEZE




A

B




TS 4000/4000 S $a \leq 1400$ mm
TS 4000 EN 5-7 $a \leq 1600$ mm



TS 4000/4000 S $a \leq 1400$ mm
TS 4000 EN 5-7 $a \leq 1600$ mm




1





i

CE	GEZE GmbH P.O. Box 1363 71226 Leonberg	12		
0672-CPD-0050	EN 1154	4	8/6/1/1/1/4	TS 4000
Substanz: -----	EN 1154	4	8/7/5/1/1/4	TS 4000 EN 5-7
	EN 1154	4	8/6/2/1/1/4	TS 4000 S


2





[mm]





4x
5x60
4x
M5x55



[mm]





4x
5x35
4x
M5x20





3x
M5x45



3



4





5








6





10 mm



i+ TS 4000





i+ TS 4000 S





7






5 mm






a (mm) - EN	
1600	7
1400	6
1250	5
1150	4
950	3
850	2
750	1





8




i+ TS 4000 S




9









i



TS 4000/4000 S a ≤ 1400 mm
TS 4000 EN 5-7 a ≤ 1600 mm



TS 4000/4000 S a ≤ 1400 mm
TS 4000 EN 5-7 a ≤ 1600 mm



GEZE GmbH
P.O.Box 1363
Reinhold-Vöster-Straße 21-29
71229 Leonberg
Germany

Tel.: 0049 7152 203-0
Fax: 0049 7152 203-310
www.geze.com

107754-02

